

GENERAL RISK ASSESSMENT

Ecoserv FM Group Limited

Stables 3, Howbery Park, OX10 8BA

Location: ESL Ltd

Title : Working at Height Risk Assessment	Date of Assessment : 10/08/2023	Risk Assessor : Stephen Jones
Risk Assessment Reference : PAD 00002/20	People involved in making this assessment : Stephen Jones	
Task/ Process : Working at Height	People at Risk : Employees	

Hazard : Work at height Whilst working at height there may be the risk of harm from someone falling.

Control Measures:

1. Safety harnesses and lanyards are used to reduce the risk of or limit injury in the event of a person actually falling. Working at Height Harness and Lanyard Checklist must be used to ascertain specific risk of falling.

Documents Associated with this Risk Assessment:	Working at Height - Tower Scaffold.pdf(Tower Scaffold) Work at Height Checklist PAD 00002-20.doc(Checklist)
Review Date : 10/08/2024	Reviewer : Peter David